




Aerial photography by Merrick and
Company, May 1980



- EXPLANATION
- 06713010 ▲ U.S.G.S. MONITORING SITE AND NUMBER
 - ◆ RAIN GAGE
 - STUDY AREA
 - 3 — SUBCATCHMENT BOUNDARY AND NUMBER
 - 24 — GUTTER OR PIPE AND NUMBER

AERIAL PHOTOGRAPH SHOWING OUTLINES OF STUDY AREA AND SUBCATCHMENTS, LOCATION OF RAIN GAGES AND MONITORING SITE FOR CHERRY KNOLLS STORM DRAIN AT DENVER, COLORADO